





N/A, IL Inspection prepared for: John Smith Date of Inspection: 6/15/2015 Age of Home: 1988 Sample report

> Inspector: Michael Doetsch License #450.000363 Barrington, IL Phone: 847-381-7210 Email: inspect@mc.net www.inspkt.com

## **General Information**

This report follows the Illinois Standards of Practice section 1410.200 of the Administrative Code. The inspection is a non-invasive examination of the readily accessible areas of the home to identify observable major defects or deficiencies existing at time of inspection as stated on the contract. No representation is made regarding areas the are hidden, obstructed, concealed or cannot been at time of inspection as stated in Section 1. of the contract. Representations regarding code, regulations, environmental concerns as stated in Section 2. of the contract are not part of this report. Please refer to all exclusions and limitations as listed in contract prior to closing escrow.

This inspection does not address the possible presence of formaldehyde, toxic, or flammable chemicals, asbestos, radon gas, lead paint, chinese drywall, or other indoor or outdoor pollutants, water or airborne related illness or disease, mold, mildew, fungi, moisture content of walls, floors, ceilings, or siding or any other substance not visually detectable, ants, birds, rodents, termites or any insect pest or wood boring organisms.

Permit verification and product recalls relating to any system or component of the property are not included. Identification of, or research for, appliances and other items that may have been recalled or have had a consumer safety alert issued about should be addressed by the Consumer Product Safety Commission. Any comments made in this report are provided as a courtesy only. Product recalls and consumer product safety alerts are added almost daily by the Consumer Product Safety Commission. We recommend visiting the following Internet site if recalls are a concern to you: http://www.cpsc.gov.

Recommend to have any concerns of the above listed items addressed by a qualified contractor contractor, prior to closing escrow.

### USE OF PHOTOS:

Photographs are included to help you better understand what is documented in this report and to help you see areas or items that you normally would not see. The pictures are informational and help you understand what was looked at and condition of the item or area at the time of the inspection. Not all problem areas or conditions will be supported with photos. One or two photos of a condition may be used to summarize similar deficiencies found at various locations. For example several joists may have been improperly cut or several damaged/rotted wood siding/trim boards may be present but only one or two photos may be taken.

## 1. Persons in Attendance

Buyer, Buyers agent, Relatives, Inspection agreement signed by buyer

### 2. Occupancy

Property is vacant.

#### 3. Property Information

• This is a single family home.

• Buyer is cautioned that this is NOT a compliance inspection. Should buyer be concerned as to municipal compliance of property a consultation with the local Municipality is recommended.

• This inspection does not review permits or determine if they exist. That determination should be made by client through the local building officials or with sellers prior to closing escrow.

## 4. Style of House

Ranch

## 5. Estimated Age

This home was built around 1988.

### 6. Weather Conditions

Temperature at the time of inspection was approximately 75-80 degrees., Cloudy, Rain today/recently

## 7. Exposure

Front of the house faces: South

### 8. Inspector

Mike Doetsch IL License #450.000363 Expires 11/30/16 Certified ASHI Member #210424

## Roof

Roofs will not be climbed during inclement weather, when slippery, high pitched or when the conditions make it unsafe or dangerous.

Many roofs are hazardous to walk on and are inspected from the ground with binoculars and from windows with a view of the roof. Some roofs, such as asbestos cement, slate, clay or concrete tile, wood shingles and shakes, may be seriously damaged by persons walking on them.

Most all homes have some form of hail damage and it is not covered by the home inspection as it is technically exhaustive. Some of the key elements an expert must examine include the type of roofing involved, weather reports during the time of loss, the average number of 'hits' per square (10' x 10' area) measured at different locations on the roof, proper installation procedures for a particular style of roof, and normal wear and tear factors associated with aging. Recommend to consult a licensed roofing contractor to determine if repairs are necessary.

Recommend to have any roof over 5 years old certified by an established local roofing contractor to determine its serviceability.

1. Roof Style

Gable

2. Roof Covering Materials

Asphalt Composition Shingles

3. Estimated Age of Roof

10-12 Years

4. Methods Used to Inspect Roof

Walked on roof


## Inspect, Inc.


5. Roof Covering Condition
Good       Fair       Poor       Unkwn       N/A         X       Image: A straight of the straight of th
6. Roof Valley Condition
Good       Fair       Poor       Unkwn       N/A         X       A       A       A       A         Observations:       • The valleys show normal wear for its age and type.
7. Soffit, Facia, Rake, and Trim Condition
Good       Fair       Poor       Unkwn       N/A         X       Appear serviceable for age and type.       • Appear serviceable for age and type.         • Conditions behind soffit and facia boards are not visible and not inspected.
8. Gutter Condition
Good       Fair       Poor       Unkwn       N/A         X       X       Materials: Aluminum         Observations:       •       •         •       Dents visible in gutters.       •         •       Gutters are sagging and need repair.       •         •       Gutters usually still need periodic cleaning with gutter guards installed.         •       Commercial downspouts are recommended for better water management.
Gutters are sagging and need repair.
9. Vent Pipe Conditions
Good       Fair       Poor       Unkwn       N/A         X       Observations:       • Exhaust vent pipe flashing has lifted and needs repair.         • Recommend repair or replacement as necessary.




Page 4 of 38









Page 5 of 38

Structural, geological certifications, hydrological stability, soil and earth measurements and stability, landslide, erosion control and earth stabilization measures, retaining walls, survey, engineer analysis, architectural, latent and concealed defects, underground utilities, flood plain certifications and surveys are not included.

Recommend to have any concerns of the above listed items addressed by a qualified contractor, prior to closing escrow.

1. Exterior Siding Condition	
Good       Fair       Poor       Unkwn       N/A         X       X       Materials: Aluminum Siding Observations:         • The siding shows normal w       • Condition of the structure b         • Condition of the structure b       • Condition of the structure b         • Damage to siding visible.       • Evidence of dents in metal         • Chalking observed.       • Recommend caulking at op         • Evidence of cracks in siding       • Loose and damaged siding         • Recommend repair or replace	vear for its age and type. behind siding cannot be determined without s and is outside the scope of this inspection. siding. pen seams. g present. g should be repaired.

Evidence of cracks in siding present.

Damage to siding visible.




Loose and damaged siding should be repaired.	Recommend caulking at open seams.		
	John Parkers		
removal of existing covering	behind trim cannot be determined without s and is outside the scope of this inspection. from windows and trim in various locations. ated and repaired around windows as necessary. In seams. I paint wood trim. eplace damaged trim. hum trim.		
Recommend to repair or	replace damaged trim.		
3. Driveway Condition			
Good         Fair         Poor         Unkwn         N/A         Materials:         Asphalt           X         Observations:	rviceable at time of inspection.		

Good Fa	ir Poor Unkwn	<ul> <li>Materials: Concrete</li> <li>Observations:         <ul> <li>Evidence of settlement in walkways with possible trip hazards present.</li> <li>Recommend evaluation by a qualified contractor for repair or replacement as necessary.</li> </ul> </li> </ul>
_		le trip hazards present. Possible trip hazards present. oop Condition
Good Fa	-	• Stoop(s) appear to be in serviceable condition at time of inspection.
Sood Fa		




Evidence of wood deterioration observed.



Evidence of nails/screws popping on the deck boards.



Evidence of wood deterioration observed.




Deck does not appear to properly supported and needs repair.



Deck does not appear to properly supported and needs repair.




Unevenness of deck indicates the possibility of frost heaving.





Flat and negative grade at foundation should be regraded.







Defective GFCI at rear exterior outlet.

## 15. Exterior Faucet Conditions



**Observations:** • Exterior faucets were serviceable at time of inspection.


## 16. Vent Jacks


Good	Fair	Poor	Unkwn	N/A	Oheenvetiene
		X			• Damaged vanes on vent jack need repair.
					<ul> <li>Damaged vent jack needs repair.</li> <li>Recommend repair or replacement as necessary.</li> </ul>



Damaged vanes on vent jack need repair.

Damaged vent jack needs repair.





#### ⊖ Observations:

Evidence of water damage and current moisture at sunroom.
Skylight at sunroom appears to have a lost thermal seal.

• Recommend evaluation for repair or replacement as necessary.



Evidence of water damage and current moisture at sunroom.

## Garage

Carage
1. Garage Type
Type: Attached, 2 car garage
2. Garage Floor Condition
Good       Fair       Poor       Unkwn       N/A         X       A       A       A       A         B       A       B       B       B       B         B       B       B       B       B       B       B         B       B       B       B       B       B       B       B         B
3. Garage Wall Condition
Good       Fair       Poor       Unkwn       N/A         X       A       A       A       A         Observations:       • Walls appear to be in serviceable condition at time of inspection.
4. Garage Ceiling Condition
Good       Fair       Poor       Unkwn       N/A         X       A       A       A       A         Observations:       • Ceiling appears to be in serviceable condition at time of inspection.
5. Overhead Garage Door Condition
Good       Fair       Poor       Unkwn       N/A         X       A       A       A       A         Observations:       • Overhead door appears to be in serviceable condition at time of inspection.

6. Garage Door Hardware Condition	
Good       Fair       Poor       Unkwn       N/A         X       Image: Non-Image: No	
7. Garage Door Opener Condition	
Good       Fair       Poor       Unkwn       N/A         X       Image: Automatic garage door opener appears to be in serviceable condition at time of inspection.         • Automatic garage door opener appears to be in serviceable condition at time of inspection.         • Safety reverse in place and operational.         • Photo eye sensors are present and working.	
8. Fire Wall and Ceiling Condition	
Good       Fair       Poor       Unkwn       N/A         X       Observations:       • Recommend to replace attic access cover in garage with 5/8" drywall.	
Recommend to replace attic access cover in garage with 5/8" drywall.	
9. Fire Door Conditions          Good       Fair       Poor       Unkwn       N/A         X       Materials:       Metal/Metal Clad         Observations:       • Recommend to install self-closing hinges as a safety feature.	
10. Garage Electrical Condition	
Good       Fair       Poor       Unkwn       N/A         X       Image: Second Control of the se	
Attic	
Entering attics that are heavily insulated can cause damage to the insulation and attic components. Attics with deep insulation cannot be safely inspected due to limited visibility of the framing members upon which the inspector must walk. Attic areas will not be traversed when there are possible safety issues present or when damage to the attic insulation or any components may occur. Insulation will Page 14 of 38	

not be disturbed during inspection.

Areas between vaulted/cathedral ceilings are not visible for inspection. Framing, decking, insulation, vapor barriers, ventilation, electrical components, etc. are not visible during inspection, and are not part of this report.

1. Methods Used to Inspect Attic			
<b>How Inspected:</b> Entering attics that are heavily insulated can cause damage to the insulation and attic components. Attics with deep insulation cannot be safely inspected due to limited visibility of the framing members upon which the inspector must walk. Inspectors will not crawl the attic area when they believe it is a danger to them or when they might damage the attic insulation or any components. This is a limited review of the attic area viewed from accessible areas only.			
2. Framing Condition			
Good       Fair       Poor       Unkwn       N/A         X       Image: Style in the structural structura s			
3. Attic Decking Condition			
Good       Fair       Poor       Unkwn       N/A         X       A       A       A       A         Observations:       • Decking appears to be structurally sound at time of inspection.			
4. Attic Insulation Condition			
Good       Fair       Poor       Unkwn       N/A         X       Materials:       Rolled/Batt insulation, Blown in insulation, Fiberglass         Observations:       • Recommend to install insulation at attic access.			
5. Attic Vapor Barrier Condition			
Good       Fair       Poor       Unkwn       N/A         X       Image: Constant of the state of t			
6. Attic Ventilation Conditions			
Good       Fair       Poor       Unkwn       N/A         X       Image: Second Structure       Image: Second Structure       Image: Second Structure         X       Image: Second Structure       Image: Second Structure       Image: Second Structure         X       Image: Second Structure       Image: Second Structure       Image: Second Structure         X       Image: Second Structure       Image: Second Structure       Image: Second Structure         X       Image: Second Structure       Image: Second Structure       Image: Second Structure         X       Image: Second Structure       Image: Second Structure       Image: Second Structure         X       Image: Second Structure       Image: Second Structure       Image: Second Structure         X       Image: Second Structure       Image: Second Structure       Image: Second Structure         X       Image: Second Structure       Image: Second Structure       Image: Second Structure         X       Image: Second Structure       Image: Second Structure       Image: Second Structure         X       Image: Second Structure       Image: Second Structure       Image: Second Structure         X       Image: Second Structure       Image: Second Structure       Image: Second Structure         X       Image: Second Structure       Imag			
• Attic appears to be properly ventilated.			
Basement			
1. Basement Stairs Condition			
Good       Fair       Poor       Unkwn       N/A         X       X       A       Becommend installing guardrails where missing.         • Recommend repair as necessary.       • Recommend repair as necessary.			

Inspect, Inc. N/A, I
Fecommend installing guardrails where missing.
2. Basement Wall Finish Condition
Good       Fair       Poor       Unkwn       N/A         X       Image: Dispersion of the service able condition of the service able condition at time of inspection.         Bood       Fair       Poor       Unkwn       N/A         X       Image: Dispersion of the service able condition at time of inspection.
3. Basement Floor Condition
Good       Fair       Poor       Unkwn       N/A         X       A       A       A       A         Bobservations:       • Flooring appears to be serviceable at time of inspection.       • Flooring appears to be serviceable at time of inspection.         • Conditions under floor finish are not visible and unable to be inspected.       • Common settlement/shrinkage cracks visible.         • Operation of the floor drain could not be confirmed at time of inspection.
4. Basement Ceiling Finish Condition
Good       Fair       Poor       Unkwn       N/A         X       A       A       A       A         Observations:       • Ceilings appear to be serviceable at time of inspection.
5. Foundation Wall Conditions
Good       Fair       Poor       Unkwn       N/A         X

## Inspect, Inc.



Evidence of seepage stains on foundation wall.

6. Joist Condition
Good       Fair       Poor       Unkwn       N/A         X       A       A       A       A       B         Observations:       •       Improper holes bored through joists.       •       Improper holes bored holes. Bored holes are usually not accepted within 2 inches of the top or bottom of the joist and should not exceed 1/3 of the depth of the joist.
<ul> <li>No appreciable deflection at time of inspection.</li> <li>Recommend repair or replacement as necessary.</li> </ul>
Improper holes bored through joists.
7. Subfloor Condition
Good       Fair       Poor       Unkwn       N/A         X       A       A       A       A         Observations:       • Visible portions of subfloor appear to be in serviceable condition.

8. Support Post Comments
Good       Fair       Poor       Unkwn       N/A         X       X       X       A       A         Observations:       • Visible portions of support posts appear to be structurally sound.         • Posts are partially finished, unable to fully inspect.       • Areas behind finished walls and floors are not visible and are not inspected.
9. Beams Condition
Good       Fair       Poor       Unkwn       N/A         X       X       X       Atterials:       Materials:       Metal         Observations:       •       •       Visible portions of beams appear to be structurally sound.       •         •       Beams are partially finished, unable to fully inspect.       •       •       Areas behind finished ceilings are not visible and are not inspected.
10. Insulation Condition
<ul> <li>Good Fair Poor Unkwn N/A</li> <li>X</li> <li>Areas behind finished walls are not visible and are not inspected.</li> <li>None observed in unfinished area.</li> </ul>
11. Window Condition
X Hair Poor Unkwn N/A Materials: Vinyl Frame, Sliding, Egress, Thermal pane Observations: • Windows appear to be in good condition at time of inspection.
12. Sump Pump Conditions
Good       Fair       Poor       Unkwn       N/A         X       Observations:       • Sump pump was working as intended.         • Pump was activated at the time of inspection, we suggest you verify operation prior to close.       • Recommend to seal cover on sump pit.         • Sump pumps are mechanical and can malfunction at anytime due to power outage, sticking float or pump failure. Battery back up system is recommended.
13. Electrical Conditions
Good       Fair       Poor       Unkwn       N/A         X       A       Becommend to add GFCI electrical outlets in unfinished basements.         • Recommend to add GFCI electrical outlets in unfinished basements.         • Evidence of amateur wiring noted.         • Exposed wires should be capped and covered.         • Recommend evaluation and repair by a licensed electrician to ensure safety.



Evidence of amateur wiring noted.

## Heating and Air Conditioning

The heating, ventilation, and air conditioning and cooling system (often referred to as HVAC) is the climate control system for the structure. The goal of these systems is to keep the occupants at a comfortable level while maintaining indoor air quality, ventilation while keeping maintenance costs at a minimum. The HVAC system is usually powered by electricity and natural gas, but can also be powered by other sources such as butane, oil, propane, solar panels, or wood.

The inspector will usually test the heating and air conditioner using the thermostat or other controls. For a more thorough investigation of the system please contact a licensed HVAC service person.

1. Type of heat
Gas Forced Air
2. Heat System Description
Good       Fair       Poor       Unkwn       N/A         X       Image: Second structure       • Number of heating units 1.       • Number of heating system is gas and the main disconnect is at the gas meter.         • Fuel source for heating system is gas and the main disconnect is at the gas meter.       • Make of furnace is Rheem.         • Estimated age of the heating system is 2009.       • The BTU on the input is 75,000 as listed on the service tag.         Observations:       • Service tag was legible.
3. Thermostat Condition
<ul> <li>Good Fair Poor Unkwn NA</li> <li>Heat and A/C have same thermostat.</li> <li>Observations:</li> <li>Thermostat was not working properly at time of inspection. Recommend to have thermostat evaluated by a qualified HVAC contractor to assure proper calibration and functional control.</li> </ul>
4. Furnace Casing Condition
Good       Fair       Poor       Unkwn       N/A         X       Observations:       • Furnace casing appear to be in good condition.
Page 19 of 38

5. Combustion Conditions	
Good       Fair       Poor       Unkwn       N/A         X       Image: State of the	nspection.
6. Gas Control Valve and Lines	
Good       Fair       Poor       Unkwn       N/A         X       Image: Construction of the second seco	ection.
7. Exhaust Venting Conditions	
Good       Fair       Poor       Unkwn       N/A         X       Image: Materials: Plastic       Observations:         • Category 1 or 4 high efficiency furnace is installed. This a category 1 type. The combustion air intake must be drated to be a category 4.	
8. Blower Fan and Motor	
Good       Fair       Poor       Unkwn       N/A         X       Image: Second sec	me of inspection.
9. Inducing Motor	
Good       Fair       Poor       Unkwn       N/A         X       Image: Second sec	pection.
10. Distribution/Ducts	
Good       Fair       Poor       Unkwn       N/A         X       A       Distribution:       • Heat and A/C have same ductwork.         Observations:       • The interior conditions of the HVAC ducts are not visible inspected.         • Any concerns regarding the inside condition of the HVA addressed by a qualified contractor.         • The condition of HVAC ducts between, behind or under floors are not visible and are not inspected.         • Recommend to have ducts cleaned by a qualified contractor.         • Ductwork system should be balanced by a licenced HV         • Duct work in basement does not appear to be adequate Comfort level may be affected due to limited number and registers.	AC ducts should be r walls, ceilings and ractor. /AC contractor. e for proper airflow.
11. Air Conditioning Comments	
Good       Fair       Poor       Unkwn       N/A         X       Image: N/A       Image: Description:       • Number of A/C units: 1.         • Fuel source for A/C is electric and the main disconnect service panel.       • Fuel source for A/C is Ruud.         • Make of A/C is Ruud.       • Estimated age of A/C compressor/condenser as per set Observations:         • Air conditioning was in serviceable condition at time of the time of time of the time of t	rvice tag is 2009. inspection.
	Page 20 of 38


WODELE N:       WARL-024JEZ       WD./THE 00/2005         SERIAL NO./ W. DE SERIE 7280030900233       ONDOR USJ DONZED FAN MOTORY       ONDOR USJ DONZED FAN MOTORY         VOLTS       200/230       PHASE. 1       REXT. 60         COMPRESSOR/ VOLTOOR FAN MOTORY       FALA. 0.3/0.3 L.R.A. 52       ONDOR FAN MOTORY         MTDER WATTLE ETT       FL.A. 0.3/0.3 L.R.A. 52       ONDOR FAN MOTORY         MTTER WATTLE ETT       FL.A. 0.3/0.3 L.R.A. 52       ONDOR FAN MOTORY         MTN. SUPPLY CIRCUIT APPACTTY/ CORMANT ADMISSIER ONLY. MN.       14/34       AVP         MW.R. DE FUSIERENDESSOR       20/20       AVP         CAL. MAR. DE FUSIERENDESSON       20/20       AVP         MM. FUSE EXERCENTES       20/20       AVP         CAL. MAR. DE FUSIERENDISSON       20/20       AVP         CONSTITUTION INFORMATION ADARTE       250       PISICIPA RESONAL CONSTITUTION ADARTE ANTON         PRESSION RAMINALE MARCE ON MARCHAR DAREXED       MARCANA       MA
Service tag.
12. Line-set Condition
X Deservations: • Line-set appears to be in serviceable condition.
13. Condensate Drain Conditions
Good Fair Poor Unkwn N/A Materials:
X PVC Piping Observations:
<ul> <li>Condensate drain is in serviceable condition at time of inspection.</li> </ul>
14. Humidifier Comments
Good       Fair       Poor       Unkwn       NA         X       A       Observations:       • A humidifier is present on the furnace. Humidifiers are beyond the scope of this inspection and are not inspected.         • Recommend to change pad in humidifier.
15. Air Filter Condition
Good       Fair       Poor       Unkwn       N/A         X       Image: Second sec
Plumbing System
The plumbing system will be observed and described only. Inspection of the plumbing system is not within the scope of the home inspection as per the Illinois Home Inspectors License Act [225 ILCS 441].
No representations are made regarding any governmental or other codes or regulations.
Plumbing Pipes within walls, ceilings, under flooring, behind, under or inside insulation, within slabs, buried under ground, hidden or obstructed are not considered visible and cannot be observed and described. Conditions existing inside of pipes are not visible and are not part of this report.
Fire suppression systems; wells, well pumps and water storage related equipment; septic and other sewage disposal systems; lawn irrigation systems; swimming pools, saunas, hot tubs, and steam showers; water conditioning systems, purifiers, reverse osmosis, hot water circulating pumps, under


sink instant hot water dispensers and the quality of water are not included within this report. These items are outside the scope of the Illinois Home Inspectors License Act [225 ILCS 441].

Concerns about any of the items mentioned above should be addressed by a licensed or qualified contractor prior to closing escrow.

contractor phor to closing escrow.
1. Plumbing System Comments
Good Fair Poor Unkwn NA • Underground supply and waste pipes are not visible and are not part of this report. Any concerns regarding these pipes should be evaluated by a licensed plumbing contractor prior to closing escrow.
<ul> <li>Limited visibility of plumbing pipes due to wall, floor and ceiling covers. Conditions of pipes in concealed, obstructed or hidden areas are not inspected and are outside the scope of this inspection.</li> </ul>
Plumbing Supply
1. Main Water Line Entry Condition
Good       Fair       Poor       Unkwn       N/A         X       A       A       Community Supply         • Copper supply pipe       • Copper supply pipe         • Main water shut off is located in basement.         Observations:         • Main gumply pipe
<ul> <li>Main supply pipe and shutoff valve appear to be in serviceable condition.</li> </ul>
2. Water Supply Line Condition
Good       Fair       Poor       Unkwn       N/A         X       A       A       A       A         Observations:       • Visible supply piping appears to be in good condition at time of inspection.         • Saddle valves are commonly used, but considered substandard.         Humidifiers & refrigerators are commonly hooked up this way.
3. Plumbing Supply Comments
<ul> <li>Good Fair Poor Unkwn N/A</li> <li>Comments:</li> <li>A water conditioning system was observed, but was not inspected. Water conditioning systems are outside the scope of a home inspection and should be evaluated by a qualified water conditioning specialist. Recommend to check for transferable warranty.</li> </ul>
Plumbing Waste
1. Main Waste Line Conditions
Good Fair Poor Unkwn N/A Service: Public Waste Observations: • Due to the number of problems many homes have with broken and obstructed pipes, it is highly recommended that the main buried sewer/waste pipes be scoped by a qualified contractor, prior to closing escrow.
Page 22 of 38

Page 22 of 38





## Inspect, Inc.

any other components which are not part of the primary electrical power distribution system as per inspection contract agreement.
Recommend to have any concerns of the above listed items addressed by a qualified contractor contractor, prior to closing escrow.
1. Service Entrance Conductor Condition
Good       Fair       Poor       Unkwn       N/A         X       Image: Construction of the service drop is underground         Observations:       • Service drop appears to be in good condition at time of inspection.
2. Electric Meter Condition
Good       Fair       Poor       Unkwn       N/A         X       Image: A structure of the
3. Amperage/Voltage and Service Panel location(s)
<ul> <li>Rating: The main service is approximately 100 amps, 240 volts.</li> <li>Location:</li> <li>Service panel and main disconnect is located in basement.</li> </ul>
4. Wiring Methods
Good       Fair       Poor       Unkwn       N/A         X       Image: Disconnect Type and Materials:       • Service disconnect is a breaker.         • Service entrance cables are aluminum.       • Service entrance cables are aluminum.         • Branch circuit wiring is copper         Wiring Style:         • Flexible metal conduit
5. Service Panel Comments
Good       Fair       Poor       Unkern       NA         Image: Strain

<image/> <image/> <caption></caption>		
6. Electric Grounding Conditions		
Good       Fair       Poor       Unkwn       N/A         X       Image: Conditions:       • Ground rod visible at electric meter.         • Electrical ground strap around water meter in place.       • Electrical ground strap at water line visible.         • Observations:       • Electrical system appears to be properly grounded.		
7. Electrical Comments		
Good       Fair       Poor       Unkwn       N/A         •       Electric system requirements vary in all municipalities and change frequently. Some components that may have been allowed once are no longer acceptable to current standards. Any concerns regarding acceptable components should be addressed by a licensed electrician.		
<ul> <li>Intercom/stereo/phone/cable/Cat5-6/alarm systems etc. are not inspected. These components are not considered part of the inspection and are not included in this report.</li> </ul>		
Kitobon		
Kitchen		
1. Kitchen Cabinet Condition		
Observations:     Water damage observed in cabinet under kitchen sink.     Damaged cabinets need repair.     Recommend review for repair or replacement as necessary.		

Damaged cabinets need repair.
2. Kitchen Countertop Condition
X     Observations:     Countertops appear to be serviceable at time of inspection.     Wear and tear of countertops is not reported.
<ul> <li>3. Kitchen Sink(s)</li> <li>Good Fair Poor Unkwn N/A</li> <li>X Observations:</li> <li>• Sink appears to be serviceable at time of inspection.</li> <li>• Wear and tear of sinks is not reported.</li> </ul>
4. Kitchen Faucet(s) and Drains
Image: Wind Wind Wind Wind Wind Wind Wind Wind
Faucet is leaking and needs repair. Possible cartridge or O-Ring.

Page 27 of 38

5. Kitchen Electrical Condition	
GFCI protected receptacle was built. Recommend upg countertop outlets where no Exposed wires under kitch Amateur wiring visible.	CI's on kitchen countertops where missing. es may not have been required when the house rading to GFCIs at all receptacles on kitchen of installed or missing. een sink. ectrician for repairs/replacement as needed to
Recommend installing GFCI's on kitchen countertops where missing.	Recommend installing GFCI's on kitchen countertops where missing.
Amateur wiring visible for exhaust fan motor.	Exposed wires under kitchen sink.


# Bathrooms

1. Counters/ Cabinets Cond	lition
• Counter • Wear an • Suggest	tions: s appear to be serviceable at time of inspection. top(s) appear to be serviceable at time of inspection. at tear of cabinets and countertops is not reported. t caulking as necessary. e of past leaking underneath bathroom sinks.
Evidence 2. Bathroom Sink Condition	e of past leaking underneath bathroom sinks.
Good Eair Boor Linkwo N/A	
X Observat • Sink(s) a • Wear an	tions: appear to be serviceable at time of inspection. Id tear of sinks is not reported. It caulking as necessary around sinks.
3. Sink Faucet Condition	
	t <b>ions:</b> cets appear to be serviceable at time of inspection. Ind tear of faucets is not reported.
4. Tub Condition	
• Whirlpoo Observat • Bathtub( • Whirlpoo check inta damage. I The items • Debris w circulation • GFCI wa	

5. Bathroom tub/shower base condition
Good       Fair       Poor       Unkwn       N/A         X       Image: Shower base appear to be serviceable at time of inspection.
6. Tub/Shower Surround
Good       Fair       Poor       Unkwn       N/A         X       Observations:       • Shower surrounds appear to be serviceable at time of inspection.         • Grout and caulk are dirty and need to be cleaned.
7. Tub/Shower Faucet Condition
Good       Fair       Poor       Unkwn       N/A         X       Image: Cool of the served of the serve of the
8. Shower Door(s)
Good       Fair       Poor       Unkwn       N/A         X       Image: Second sec
9. Toilet Condition
Good       Fair       Poor       Unkwn       N/A         X       Image: Cool of the service and the service able at time of the service able at time at time at the service able at time at the service able at time at the service able at time at the service at the service able at the service at the
10. Bathroom Exhaust Fan Condition
Good       Fair       Poor       Unkwn       N/A         X       Image: Cool of the served of the serve of the
11. Electrical Condition
Good       Fair       Poor       Unkwn       N/A         X       Image: Cool of the second secon
Laundry Room
1. Laundry Area Location
Location: Basement
2. Laundry Tub/Sink Condition
X     Plastic     Observations:         • Laundry sink appears to be serviceable at time of inspection.
3. Washing Machine Conditions
Good       Fair       Poor       Unkwn       N/A         X       A       A       B
<ul> <li>The washing machine is near the end of its useful life.</li> </ul>
Page 30 of 38

Good

Fair



Recommend solid walled metal pipe for dryer vent.

# Interior

Please review the following for some of the systems and components that are not included in the inspection:

Floors, walls, ceilings, stairs, doors, and windows are checked for structural stability, safety and habitability issues and basic function only. Settlement cracks, holes, damaged and repaired coverings are not included.

Paint, wallpaper, and other finish treatments: floor coverings; window treatments; remote control devices; concealed conditions, latent defects, consequential damages, and cosmetic imperfections that do not significantly affect a component's performance of its intended function are not included.

Coatings on and faulty hermetic (thermal pane) seals on window panes are not included in this report. Fogging between window panes are not always visible. Conditions indicating a broken seal are not always visible or present and may not be apparent or visible at the time of inspection. Changing conditions such as temperature, humidity, and lighting limit the ability to visually review these windows for broken seals. For more complete information on the condition of all thermal pane windows, consult with a professional window installer with any related concerns.

The adequacy and efficency of systems and components are not included.

Fireplace and fuel burning appliances are checked for basic operation and safety where visible only. Interiors of vent systems, flues and chimneys that are not readily accessible or visible are not included. Fire screens, doors, seals, gaskets, mantles and fireplace surrounds are not included. Automatic fuel feed devices; combustion air components or their adequacy; heat distribution assists (gravity fed and fan assisted); and remote controls are not included.

Recommend to have any concerns of the above listed items addressed by a qualified contractor contractor, prior to closing escrow. Floor Condition Fair Poor Unkwn Good Observations: Х Floors appear to be serviceable at time of inspection. Wear and tear of flooring is not reported. Evidence of stains discoloration on carpeting. Floors squeak due to subfloor and nail movement. 2. Wall Condition Unkwn Good Fair Poor N/A Observations: Х Walls appear to be serviceable at time of inspection. Wear and tear of walls is not reported. Settlement cracks visible on walls. 3. Ceiling Conditions Fair Poor Unkwn Good Observations: Х Ceilings appear to be serviceable at time of inspection. Evidence of nail pops and cracks visible in ceiling due to truss uplift. 4. Door Conditions Poor Unkwn Good Fair N/A Observations: Х Interior doors appear to be serviceable at time of inspection. Wear and tear of doors is not reported. Some interior doors need adjustment or repair. Hardware needs repair. Some doors do not latch/lock and need repair. Recommend repair or replacement as necessary. 5. Window Frame Conditions Fair Poor Unkwn Good Style: Thermal pane Windows, Fixed , Double Hung, Vinyl Frame Х **Observations:**  Window frames appear to be in good condition for age and type. Window treatments are not inspected. 6. Window Glazing Condition Fair Poor Unkwn N/A Good **Observations:** Х Thermal pane windows observed in the home: Detection of lost/failed thermal seals is outside the scope of this inspection. Conditions indicating a lost thermal seal are not always visible or present and may not be apparent or visible at the time of inspection. Changing conditions such as temperature, humidity and lighting limit the ability to visually evaluate windows for failed thermal seals. Recommend to consult with a qualified window contractor with any related concerns regarding the condition of thermal pane windows and their energy efficiency. Reference to any lost thermal seals listed in this report are considered a courtesy.

• Lost seal in master bedroom.

• Recommend review by a qualified professional for repair or replacement as necessary.

## Inspect, Inc.



Lost seal in master bedroom.

## 7. Smoke Detectors

Good	Fair	Poor	Unkwn	N/A	
					Obse
X					l•Smo

## • Smoke detectors are serviceable at time of inspection.

## 8. Carbon Monoxide Detectors

Good Fair Poor Unkwn N/A

**Observations:** • Carbon monoxide detectors are serviceable at time of inspection.

## 9. Electrical Condition

Good       Fair       Poor       Unkwn       N/A         X       Image: Second Hight Fixtures recommended in closets.         • Fluorescent light fixtures recommended in closets.         • Exposed bulbs in closet should be covered.
Exposed bulbs in closet should be covered.

10. Fireplace Location

#### Location:

• The fireplace is located in the living room.

11. Fireplace Style
Style: • Masonry
12. Fireplace Comments
Good       Fair       Poor       Unkwn       N/A         X       Image: Service able at time of inspection.
13. Other Interior Area Comments
Good Fair Poor Unkwn N/A X Deservations: • The main intention of this report is to identify latent safety or habitability issues along with major operational defects and areas of necessary repair. With this in mind we have purposefully overlooked things such as worn flooring, paint, holes, patchwork, etc. on floors, walls, ceilings, doors and windows. Any remarks regarding the condition are considered a courtesy.
• The presence of mold on or behind wall coverings, furniture, personal storage or in any other concealed area of the home is not part of this inspection. Any concerns about visible or hidden mold should be addressed by a licensed environmental inspector prior to closing escrow. Any remarks regarding the possibility of mold are considered a courtesy.
<ul> <li>The presence of wood destroying insects and pests is outside the scope of this inspection. Recommend evaluation by a qualified pest control operator for evaluation and treatment as necessary if concerned, prior to closing escrow. Any remarks are considered a courtesy.</li> </ul>
<ul> <li>Possible environmental hazards may be present. Detection or inspection for the presence of environmental hazards such as asbestos, lead, radon, formaldehyde, EMF, toxic or flammable chemicals or any other potentially harmful substances are NOT part of this report. Recommend to consult a licensed environmental inspector regarding the possible presence and condition of these prior to closing escrow. Any remarks are considered a courtesy.</li> </ul>
<ul> <li>Paint, wallpaper, drywall, window treatments, coatings on and the hermetic seals between panes of window glass are not inspected. Any remarks regarding the condition are considered a courtesy.</li> </ul>
<ul> <li>Missing insulation on outside wall under whirlpool tub. Recommend to have exterior wall insulated by a qualified contractor.</li> </ul>



Missing insulation on outside wall under whirlpool tub.

## Appliances

Built-in appliances are evaluated for basic operation and defects only. Free standing appliances are not inspected. Built-in appliances are tested using normal operating controls to activate the primary function only. Operation or performance of special features such as timers, clocks, indicator lights, thermostats, programmed cycles, self cleaning oven cycles, or proper calibration are not evaluated. Recommend to have any concerns of the above listed items addressed by a qualified contractor, prior to closing escrow.

## 1. Stove Cooktop Conditions

1. Stove Cooktop Conditions
Good       Fair       Poor       Unkwn       N/A         X       A       Built in       A         Observations:       • Built in       Built in         Observations:       • Working at time of inspection. Recommend to check again on final walk through prior to closing escrow.         • The stove/cooktop is near the end of its useful life.
2. Oven Conditions
Good       Fair       Poor       Unkwn       N/A         X       X       Benergy Source:       Gas         Observations:       • Working at time of inspection. Recommend to check again on final walk through prior to closing escrow.         • The oven is near the end of its useful life.
3. Dishwasher Condition
Good         Fair         Poor         Unkwn         N/A           X         Image: Second Control of Co
4. Kitchen Vent Condition
Good Fair Poor Unkwn NA X Dbservations: • Appears to be wired with extension cord. • Recommend evaluation by a professional appliance repair specialist.
Page 35 of 38

Inspect, Inc.	N/A, II
5. Refrigerator/ Freezer Comments	
Good Fair Poor Unkwn N/A X • Refrigerator/Freezer unplugged at time of inspection.	
Rodent	
1. Rodent Activity	
Cord       Fair       Poor       Unkwn       NA         Diservations:       • Evidence of possible bees nests and honey combs visible at various an         • Evidence of ant infestation visible.       • While this is NOT a pest inspection, there were visible signs of pest acting present.         • Recommend evaluation by a professional pest control operator.         • The second evaluation by a professional pest control operator.         • Evidence of ant infestation visible.         • Recommend evaluation by a professional pest control operator.         • Evidence of ant infestation visible.         • Recommend evaluation by a professional pest control operator.	

Evidence of ant infestation visible.

# **REPORT SUMMARY**

The summary below consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expense to correct or items I would like to draw extra attention to. The summary is not a complete listing of all the findings in the report, and reflects the opinion of the inspector. Please review all pages of the report as the summary alone does not explain all of the issues. All repairs should be done by a licensed & bonded tradesman or qualified professional. I recommend obtaining a copy of all receipts, warranties and permits for the work done.

Exterior			
Page 8 Item: 4	Walkway Conditions	<ul> <li>Evidence of settlement in walkways with possible trip hazards present.</li> <li>Recommend evaluation by a qualified contractor for repair or replacement as necessary.</li> </ul>	
Page 8 Item: 6	Deck Condition	<ul> <li>Unevenness of deck indicates the possibility of frost heaving.</li> <li>Evidence of nails/screws popping on the deck boards.</li> <li>Deck materials are weathered with curling, cupping, cracks, splits etc. and need repair.</li> <li>Evidence of wood deterioration observed.</li> <li>Deck does not appear to properly supported and needs repair.</li> <li>Evidence of some type of unknown cinderblock foundation under deck structure.</li> <li>Recommend evaluation by a qualified contractor for repair or replacement as necessary.</li> </ul>	
Page 10 Item: 12	Lot Grade and Drainage Conditions	• Flat and negative grade at foundation should be regraded and sloped away from house. Regrading around the foundation is recommended to ensure proper drainage away from the foundation at all times.	
Page 12 Item: 14	Exterior Electrical Conditions	<ul> <li>GFCI at North side of house had power when tripped. This is often the result of improper wiring and should be repaired by a licensed electrician.</li> <li>Lamp post was not working at time of inspection.</li> <li>Recommend evaluation for repair or replacement by a licensed electrician as necessary.</li> </ul>	
Page 12 Item: 16	Vent Jacks	<ul> <li>Damaged vanes on vent jack need repair.</li> <li>Damaged vent jack needs repair.</li> <li>Recommend repair or replacement as necessary.</li> </ul>	
Page 12 Item: 17	General Exterior Comments	<ul> <li>Evidence of water damage and current moisture at sunroom.</li> <li>Skylight at sunroom appears to have a lost thermal seal.</li> <li>Recommend evaluation for repair or replacement as necessary.</li> </ul>	
Garage			
Page 14 Item: 8	Fire Wall and Ceiling Condition	• Recommend to replace attic access cover in garage with 5/8" drywall.	
Basement			
Page 15 Item: 1	Basement Stairs Condition	<ul> <li>Recommend installing guardrails where missing.</li> <li>Recommend repair as necessary.</li> </ul>	

Page 16 Item: 5	Foundation Wall Conditions	<ul> <li>Evidence of seepage stains on foundation wall.</li> <li>Recommend to have foundation walls evaluated and repaired by a professional waterproofing contractor.</li> </ul>
Page 18 Item: 13	Electrical Conditions	<ul> <li>Evidence of amateur wiring noted.</li> <li>Exposed wires should be capped and covered.</li> <li>Recommend evaluation and repair by a licensed electrician to ensure safety.</li> </ul>
Heating and Air	Conditioning	
Page 19 Item: 3	Thermostat Condition	• Thermostat was not working properly at time of inspection. Recommend to have thermostat evaluated by a qualified HVAC contractor to assure proper calibration and functional control.
Plumbing Wast	e	
Page 23 Item: 3	Ejector Pump Conditions	<ul> <li>Ejector pit should be completely sealed.</li> <li>Recommend review by a licensed plumber for repair or replacement, as necessary.</li> </ul>
Electrical	_	
Page 25 Item: 5	Service Panel Comments	Overfusing at circuit disconnect observed.
Kitchen	1	
Page 27 Item: 4	Kitchen Faucet(s) and Drains	<ul> <li>Faucet is leaking and needs repair. Possible cartridge or O-Ring.</li> <li>Recommend to have repaired or replaced by a licensed plumbing contractor as necessary.</li> </ul>
Page 28 Item: 5	Kitchen Electrical Condition	<ul> <li>GFCI protected receptacles may not have been required when the house was built. Recommend upgrading to GFCIs at all receptacles on kitchen countertop outlets where not installed or missing.</li> <li>Exposed wires under kitchen sink.</li> <li>Amateur wiring visible.</li> <li>Recommend a licensed electrician for repairs/replacement as needed to ensure safety.</li> </ul>
Laundry Room		
Page 31 Item: 4	Dryer Conditions	<ul> <li>Recommend solid walled metal pipe for dryer vent.</li> <li>Recommend repair as necessary.</li> </ul>
Interior		
Page 32 Item: 6	Window Glazing Condition	<ul> <li>Lost seal in master bedroom.</li> <li>Recommend review by a qualified professional for repair or replacement as necessary.</li> </ul>
Page 34 Item: 13	Other Interior Area Comments	• Missing insulation on outside wall under whirlpool tub. Recommend to have exterior wall insulated by a qualified contractor.
Appliances		
Page 36 Item: 4	Kitchen Vent Condition	<ul> <li>Appears to be wired with extension cord.</li> <li>Recommend evaluation by a professional appliance repair specialist.</li> </ul>